	Туре	Hits	Search Text	DBs	Time Stamp
1	IS&R	410	(228/121).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/08/25 12:37
2	IS&R	605	(228/234.1).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/08/25 12:26
3	IS&R	462	(228/235.1).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/08/25 12:26
4	IS&R	361	(228/262.1).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/08/25 12:27
5	IS&R	380	(228/262.5).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/08/25 12:27
6	IS&R	526	(228/262.51).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/08/25 12:28
7	IS&R	1337	(156/272.2).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/08/25 12:29
8	IS&R	531	(156/272.8).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/08/25 12:30
9	IS&R	284	(156/273.7).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/08/25 12:30
10	IS&R	4049 8 .	("228").CLAS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/08/25 12:37
11	IS&R	1144 97	("156").CLAS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/08/25 12:38

	Туре	Hits	Search Text	DBs	Time Stamp
12	BRS	1537 54	S10 or S11	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/08/25 12:38
13	BRS	6728	\$12 and ((compress\$3 or press\$3 or force) near20 (bond\$3 or solder\$3 or braz\$3)) near50 (layer or coat\$3 or film)	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/08/25 12:41
14	BRS	228	\$12 and ((compress\$3 or press\$3 or force) near20 (bond\$3 or solder\$3 or braz\$3)) near50 (layer or coat\$3 or film) near100 (light or laser or ultraviolet or UV)	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/08/25 12:42
15	BRS	232	\$12 and ((compress\$3 or press\$3 or force) near20 (bond\$3 or solder\$3 or braz\$3)) near50 ((layer or coat\$3 or film) near50 (strip\$2 or dot\$1 or pattern\$1)) and (light or laser or ultraviolet or UV)	EPO; JPO; DERWENT	2006/08/25 12:43

	Туре	Hits	Search Text	DBs	Time Stamp
16	BRS	17	S12 and ((compress\$3 or press\$3 or force) near20 (bond\$3 or solder\$3 or braz\$3)) near50 ((layer or coat\$3 or film) near50 (strip\$2 or dot\$1 or pattern\$1)) near200 (light or laser or ultraviolet or UV or irradiat\$3)	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/08/25 12:50
17	BRS	149	((compress\$3 or press\$3 or force) near20 (bond\$3 or solder\$3 or braz\$3)) near50 ((layer or coat\$3 or film) near50 (strip\$2 or dot\$1 or pattern\$1)) near200 (light or laser or ultraviolet or UV or irradiat\$3)	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/08/25 12:50

	Туре	Hits	Search Text	DBs	Time Stamp
18	BRS	107	((compress\$3 or press\$3 or force) near10 (bond\$3 or solder\$3 or braz\$3)) near20 ((layer or coat\$3 or film) near50 (strip\$2 or dot\$1 or pattern\$1)) near100 (light or laser or ultraviolet or UV or irradiat\$3)	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/08/25 12:56
19	BRS	577	(((compress\$3 or press\$3 or force) near50 (bond\$3 or solder\$3 or braz\$3)) near50 ((layer or coat\$3 or film) near50 (strip\$2 or dot\$1 or pattern\$1)) near50 (metal or alloy))	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/08/25 12:57

	Туре	Hits	Search Text	DBs	Time Stamp
20	BRS	198	(((compress\$3 or press\$3 or force) near50 (bond\$3 or solder\$3 or braz\$3)) near50 ((layer or coat\$3 or film) near50 (strip\$2 or dot\$1 or pattern\$1)) near50 (metal or alloy)) and (laser or light or ultraviolet or UV or irradiat\$3)	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/08/25 12:58
21	BRS	11	near50 (strip\$2 or	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/08/25 13:00

	Туре	Hits	Search Text	DBs	Time Stamp
22	BRS	14	(((\$6compress\$3 or press\$3 or force) near50 (bond\$3 or solder\$3 or braz\$3)) near50 ((layer or coat\$3 or film) near50 (strip\$2 or dot\$1 or pattern\$1)) near50 (metal or alloy)) near200 (laser or light or ultraviolet or UV or irradiat\$3)	US-PGPUB; USPAT; EPO; JPO;	2006/08/25 13:02
23	BRS	0	((((\$6compress\$3 or press\$3 or force) near50 (bond\$3 or solder\$3 or braz\$3)) near50 ((layer or coat\$3 or film) near50 (strip\$2 or dot\$1 or pattern\$1)) near50 (metal or alloy)) near200 (laser or light or ultraviolet or UV or irradiat\$3)).clm.	US-PGPUB; USPAT	2006/08/25 13:02

_	Туре	Hits	Search Text	DBs	Time Stamp
24	BRS	67	((((\$6compress\$3 or press\$3 or force) near50 (bond\$3 or solder\$3 or braz\$3)) near50 ((layer or coat\$3 or film) near50 (strip\$2 or dot\$1 or pattern\$1)) near50 (metal or alloy)).clm.	US-PGPUB; USPAT	2006/08/25 13:08
25	BRS	10	((((\$6compress\$3 or press\$3 or force) near50 (bond\$3 or solder\$3 or braz\$3)) near50 ((layer or coat\$3 or film) near50 (strip\$2 or dot\$1 or pattern\$1)) near50 (light or laser or ultraviolet or UV or irradiat\$3))).clm.	US-PGPUB; USPAT	2006/08/25 13:09

	Туре	Hits	Search Text	DBs	Time Stamp
26	BRS	10	((((\$6compress\$3 or press\$3 or force) near50 (bond\$3 or solder\$3 or braz\$3)) near50 ((layer or coat\$3 or film) near50 (strip\$2 or dot\$1 or pattern\$1 or mask or stencil)) near50 (light or laser or ultraviolet or UV or irradiat\$3))).clm.	US-PGPUB; USPAT	2006/08/25 13:09
27	BRS	414	((((\$6compress\$3 or press\$3 or force) near20 (bond\$3 or solder\$3 or braz\$3)) near20 ((layer or coat\$3 or film) near20 (strip\$2 or dot\$1 or pattern\$1 or mask or stencil)))).clm.	US-PGPUB; USPAT	2006/08/25 13:10

	Туре	Hits	Search Text	DBs	Time Stamp
28	BRS	51	((((\$6compress\$3 or press\$3 or force) near20 (bond\$3 or solder\$3 or braz\$3)) near20 ((layer or coat\$3 or film) near20 (strip\$2 or dot\$1 or pattern\$1 or mask or stencil) near20 (metal or alloy))).clm.		2006/08/25 13:10